

Descriptor	Summary
Accessories	Updated - Configuration work for G2.5 Impeller Balancing (DCR-2024-006)
	Updated - iFMS Riser Size based on Velocity (DCR-2023-006)
Boosters	Resolved - Booster Pump Replacement Drive - inaccurate List Price and Total Price display (All Markets)
	Resolved - Getting report error for DE Booster Submittal (All Markets)
	Resolved - Grid Price is always displayed as CFP (Call for Pricing) for Standalone booster pumps (APR market)
	Resolved - Incorrect description displayed post select. (India Market)
	Validated - 11 kW Booster motor efficiency in ADEPT printed quotes (Incident #120369)
Controls	Updated - Data for North American-sourced IPC9511 and IPC9521 (Incident #119363)
Expansion Tank	Validated - Expansion vessel unit of measurement in printed ADEPT PDF proposals (Incident #120344)
	Validated - Non ASME Expansion Tanks and Non ASME Air Separators Lead time (India) (Incident #120352)
Fire Systems	Updated - Fire pump Nameplate Selection (Incident #118745)
	Validated - Shipment Indicator for Fire System (UK) (Incident #119827)
General	Removed - 'Report an issue' hyperlink in ADEPT Quote banner
	Updated - ADEPT Select Login Window verbiage (Incident #118130)
	Updated - Copyright Date (Incident #118749)
OEM	Updated - Daikin 4200H filtering issue
Order Submission	Added - Promotion Codes (All Markets)
	Resolved - ERP ID error Goble Switch London (Incident #120654)
	Resolved - S&T Configurator Shipment indicator (Incident #115796)
	Updated - Consult Factory Workflow to run on place order
	Updated - Lead times (Incident #116529)
	Updated - Shipment Indicator for SG/FTV - Supplied from AIL (Incident #118194)
	Validated - 10S016902 - Critical Project - SAA-Oakes Enterprises Sales And Service (Incident #120386)
Pumps	Validated - ADEPT Payment Information
	Added - Dev engine/Configuration for Medium Pump ES 6-inch (DCR-2024-011)
	Added - Medium Pumps ES 4200H models set to PreLaunch Status
	Added - Previously Removed and Discontinued Pumps
	Added - Re-instate More DE pump selections
	Configured - Pump Part # GEN3SERVICEKITS (Incident #119912)
	Corrected - Curve and Motor Line for VMS-64 models -NEMA (DCR-2024-003)
	Launch - Enable Manual select for the new Medium Pump Tango & SGs (DCR-2024-009)
	Launch - Medium Pump Tango & SGs (DCR-2024-009)
	Launch - New Engine work for Medium Pump ES 6-inch (DCR-2024-011)
Launch - Pacdor work for Medium Pump Tango & SGs (DCR-2024-009)	
Removed - Frame size dependency from development engine	

Descriptor	Summary
Pumps	Removed - Replacement Drive - sensorless adder
	Resolved - 2D Drawing issue regarding the 4300DE 125-290 11kW (Incident 89574)
	Resolved - 4030 6x5x11.5 at 25 HP 1800 RPM in All Iron construction (with brine fluid), using OEM method (Incident #119223)
	Resolved - Curve ID mismatch between CS vs VS pump
	Resolved - Getting error for Conventional Pump Series 1050 and 1060 (NEMA Market)
	Resolved - Issues with Buy American and Baldor option
	Resolved - OH3 15M should be a VMS2-09 (Incident #120689)
	Resolved - Pump Manager Pricing (Incident #117632)
	Resolved - Pumps VS all series showing price +NCP (ME market)
	Updated - DEPM to DEPM2 for Gen5 Pumps (Incident #120573)
	Updated - Motor lines for 4030-'150-330' size
	Updated - Price for Tangos up to 10hp (USA and LATAM)
	Updated - YLAA pump routing text (Incident #118542)
	Validated - Negative value for the Pump Weight - VS
Selection	Added - Configuration Turndown ratio
	Corrected - Medium Pump - DE4332 - Add to schedule button does not disable, when click outside curve envelope
	Resolved - "Attention Required" message displayed VS pumps (CA, US)
TM65	Updated - TM65 report data